

Software Name: VPort ActiveX SDK PLUS

Version No.	Build Code	Supported OS	Apply to (full model name)	New Feature(s)	Change(s)	Enhancement(s)	Bug(s) Fixed	Additional Note(s)
2.9	17032817	Windows XP with SP3 Windows 7	VPort 351 VPort 354 VPort 354 VPort 461 VPort 461 VPort 36-1MP VPort 36-1MP VPort 36-1MP VPort 56-2MP VPort 106-1MP-M12 VPort 106-1C-1MP-M12 VPort 106-1C-1MP-M12 VPort 106-1MP-M12 VPort 106-1MP-M12 VPort 16-1MP-M12 VPort 16-1MP-M12 VPort 16-1MP-M12 VPort 16-1MP-M12 VPort 16-1MP-M12 VPort 16-1MP-M12 VPort 196-3MP VPort 196-3MP VPort 196-3MP VPort 196-3MP VPort 196-3MR VPort 196-3MR	Support UTF8 code page for customized caption feature of Vport 461A. Add a new event driven interface GetReceiveFrameRate() for getting received figs information. Support 64 bit version SDK.	Limit max record file size to 1GB and auto split it if exceeded.		Fix record functionality fail issue in tha case that user use 3rd party camera streaming uri to coneect steaming. Fix continuous record frame dropped issue. Fix Digital-PTZ cannot work if enabling it in the meantime of building streaming.	N/A
2.9	16060310	Windows XP with SP3 Windows 7	VPort 351 VPort 351 VPort 451 VPort 451 VPort 461 VPort 461 VPort 364A VPort 364A VPort 364A VPort 364A VPort 964A VPort 964A VPort P06-1MP VPort P06-MP VPort P16-MP VPort P16-MP VPort P16-MP VPort P16-MP VPort P16-MP	Support AAC audio decoder and rendering. Support HTTP Digest authorization of HTTP command interface. Support Digital PTZ. a. Mouse wheel: Zoom in/out. b. Mouse drag and drop: Pan and Tilt. c. Right-button mouse click: Restore to original frame. Support pb2312 code page for TMRT 371 06-2MP, 16-2MP, and 06-HC-2MP models to render Chinese wording on caption bar.	Setup media service URI automatically if user doesn't fill it. Fix GDI flict for Audio post case.	ker problem under RGB rendering mode.	1. Fix Audio post function takes more than 8 seconds to enable. 2. Prevent unexpected crash when received frame is too large. 3. Fix Ul thread may be blocked in connection function for long time if target IP address isn't available. 4. Fix an issue that ActiveX SDK in browser cannot display IP cam's video properly if device is behind NAT. 5. Fix potential crash when drawing on windows DC. 6. Fix application may hang if the peer IP address sin't exist. 7. Fix memory leak problem in GDI graphic rendering mode. 8. Fix memory leak issue when repeatedly connect and disconnect. 9. When codes is NUPEG, the displayed alert line of VMDI is wrong. 10. Fix VPDT 364A audio post does not work issue. 11. Fix audio post would be failed if authentication is eanbled. 11. Fix audio post would be failed if authentication is eanbled. 11. Fix the surfaciation Dislog will pop-up repeatedly when enabling Auto-Reconnect functionality. 13. Fix that terminate ActiveX plug-in may take long time after camera was disconnected when enabling "auto-reconnect" mechanism. 14. Fix cannot record audio only steam in AVI format correctly. 15. Fix cannot connect under RTSP over HTTP protocol.	N/A
2.8	15030915	Windows XP with SP3 Windows 7	VPort 351 VPort 354 VPort 451 VPort 461 VPort 361 VPort 36-14M VPort 36-14M VPort 56-2MP VPort D66-1MP-M12 VPort P66-1-MP-M12 VPort 66-2	N/A	N/A	N/A	Fix a potential security issue.	N/A
v2.8	14112513	Windows XP with SP3 Windows 7	VPort 351 VPort 354 VPort 451 VPort 461 VPort 364A VPort 364-1MP VPort 264-1MP VPort 56-2MP VPort 766-1MP-M12 VPort 966-1MP-M12 VPort 966-1MP-M12 VPort 966-1MP-M12 VPort 966-1MP-M12	N/A	When Audio Post is occupied, another caller has to popup an error dialog. Setup media service URI automatically if user doesn't fill on multi-cord to do Audio post.		Fix Multi-thread crash issue in audio push module(MxAudio). Fix an exception in Motion Edit mode. Toesn't send force I-frame CGI to server when connect with multicast push protocol. Audio post functionality expend too long time to enable.(8 seconds) Cannot connect with Lilin PTZ camera with multicast protocol. Buffer overflow issue in dummy sink frame receiving socket. Ul thread may be blocked in connection function for long time if target IP address isn't available.	N/A
2.8	14052616	Windows XP with SP3 Windows 7	VPort 351 VPort 354 VPort 451 VPort 461 VPort 36-4M VPort 36-1MP VPort 56-MP-W12 VPort 96-6MP-M12 VPort 66-6MP-M12 VPort 66-6MP-M12 VPort 66-6MP-M12 VPort 66-6MP-M12 VPort 66-6MP-M12	N/A	Need to input user authentication data every time after digest authentication is enabled User authentication failed after server change HTTP/RTSP authentication scheme from basic to digest.	N/A	Fixed unable to connect to VPort 351 with MPEG4 via multicast The installation time is longer than the previously	N/A



Software Name: VPort ActiveX SDK PLUS

Ver	rsion No.	Build Code	Supported OS	Apply to (full model name)	New Feature(s)	Change(s)	Enhancement(s)	Bug(s) Fixed	Additional Note(s)
	2.8	14032812	Windows XP with SP3 Windows 7	VPort P06HC-1MP-M12	Support MOXA ONVIF Profile S devices Add new properties, MediaServiceUri, ProfileToken, StreamUri, for ONVIF connection 3. Add new method, SetMulticastInfoByType, for multicast push protocol 4. Add define, EMulticastInfoByType, for SetMulticastInfoByType function 5. Support RTSP MJPEG and parsing MJPEG comment segment 6. Parsing timezone information in user data 7. Add new property, VersionInfo, to get product version string in resource file 8. Integrate with MxAudio library to support audio post and ONVIF backchannel handling 9. Description of VPort RTSP streaming URI definition, RTSP connection rules and Microsoft NET Framework integration issue in the appendix section	N/A	1. Modified ERecordedStatus due to an invalid recording path or file openwirten being failed 2. Parse the server IP, the port number, the user information from the URI of an input RTSP streaming or the URI of an ONVIF Modia Service 3. Definition of EMulticastInfoType in ActiveX interface 4. Prevent HD video frame dropping 5. Add correct NULL padding in a recording AVI file chunk	1. Graphic objects didn't resize after window had changed the size 2. Couldn't modify VMD's window name, percentage and sensitivity when VMD was disabled 3. Visual C++ 2005 Redistributable reinstalled every time 4. Couldn't display graphic objects 5. VPOT ActiveX SDK sent an unexpected CGI command 6. Couldn't show the status, connect fall, when a server's connection was full 7. Recording settings in the disconnect callback was discarded 8. Couldn't disconnect correctly when the connection with the streaming server had broken down 9. Crashed in IEG browser when motion edit mode was enabled 10. Couldn't decode the multicast-push-MJPEG stream 11. IE freezed when the server became unreachable	N/A