

# Linux Kernel 4.x.x Driver for Multiport Serial PCI Express and Universal PCI Boards Release Notes

Version: v4.2 Build: 220722176

Release Date: Jan 17, 2023

# **Applicable Products**

CP-102E/102EL Series, CP-102N Series, CP-102U/102UL Series, CP-104EL-A Series, CP-104N Series, CP-104UL/104JU Series, CP-112UL Series, CP-114EL Series, CP-114N Series, CP-114UL Series, CP-116E-A, CP-118E-A-I/138E-A-I Series, CP-118EL-A, CP-118U/138U Series, CP-132EL Series, CP-132N Series, CP-132UL Series, CP-134EL-A-I Series, CP-134N Series, CP-134U Series, CP-168EL-A, CP-168U Series, POS-104UL Series

## **Supported Operating Systems**

Linux Kernel 4.x

## **New Features**

• Supports Mini PCIe Serial Boards: CP-102N, CP-132N, CP-104N, CP-134N, and CP-114N Series.

#### **Enhancements**

N/A

# **Bugs Fixed**

- A compilation error where 3 arguments were passed but only 2 were used in Kylin Linux.
- A compiling error in RHEL 8.5 system caused by the kernel changing the type and name definition task struct::state.

## Changes

N/A

#### **Notes**

N/A



Version: v4.1 Build: 21102516

Release Date: Oct 25, 2021

## **Applicable Products**

CP-132UL Series, CP-134N Series, CP-168EL-A, CP-134EL-A-I Series, CP-602E-I Series, CP-132EL Series, CP-118EL-A, CP-118E-A-I/138E-A-I Series, POS-104UL Series, CP-102N Series, CP-114UL Series, CP-118U/138U Series, CP-102U/102UL Series, CP-112UL Series, CP-134U Series, CP-104N Series, CP-102E/102EL Series, CP-114EL Series, CP-104UL/104JU Series, CP-168U Series, CP-602U-I Series, CP-116E-A, CP-132N Series, CP-104EL-A Series, CP-114N Series

# **Supported Operating Systems**

Linux Kernel 4.x

#### **New Features**

• Supports x86/x64 Arm platform.

#### **Enhancements**

N/A

## **Bugs Fixed**

- Baud rate mismatches when built-in kernel module "8250\_moxa" is running.
- Compiling the driver in a RHEL8 system returns the error "access\_ok passed 3 arguments but takes just 2".
- Driver cannot be loaded by rc.mxser in a RHEL8 system.
- The muestry command could not set the device's serial interface type to RS-232.
- The tty ports in the device cannot be scanned by third-party utilities implemented using the QT serial ports library (e.g., CuteCom).
- Compile error "File is in the wrong format" when compiling utilities.
- Compile error "ASYNCB\_ undeclared" in Debian 9 (kernel 4.9).

## **Changes**

- Downgrades software license from GPLv3 to GPLv2.
- Avoids using mxinstall when compiling utilities that are not supported in the Arm platform.

## **Notes**

N/A



Version: v4.0 Build: 19090215

Release Date: Dec 31, 2019

# **Applicable Products**

CP-118E-A-I/138E-A-I Series, CP-134EL-A-I Series, CP-116E-A, CP-102E/102EL Series, CP-104EL-A Series, CP-168EL-A, CP-132EL Series, CP-114EL Series, CP-118EL-A, CP-102U/102UL Series, CP-104UL/104JU Series, CP-168U Series, POS-104UL Series, CP-132UL Series, CP-134U Series, CP-112UL Series, CP-114UL Series, CP-118U/138U Series

# **Supported Operating Systems**

Linux Kernel 4.x

## **New Features**

• First release.

## **Enhancements**

N/A

# **Bugs Fixed**

N/A

# **Changes**

N/A

## **Notes**

N/A