



## Firmware for EDR-G9010 Series Release Notes

<b>Version: v2.1</b>	<b>Build: 22122916</b>
<b>Release Date: Jan 09, 2023</b>	

### **Applicable Products**

N/A

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

N/A

### **Bugs Fixed**

- IPsec over L2TP behaves abnormally if IPsec settings have been configured previously.
- Static routing does not work properly after enabling dynamic routing.
- The OSPF current router ID displays incorrectly after rebooting the device.
- The Turbo Ring becomes unstable after enabling the NTP/SNTP server.

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v2.0.1</b>	<b>Build: 22101419</b>
<b>Release Date: Oct 20, 2022</b>	

**Applicable Products**

N/A

**Supported Operating Systems**

N/A

**New Features**

N/A

**Enhancements**

N/A

**Bugs Fixed**

- Layer 3-7 firewall policies behave abnormally after deploying the policy profile through MXsecurity.
- The system is unable to get the MXsecurity Agent Package information after booting the device.
- Users are unable to import configurations after changing the event log threshold settings.

**Changes**

N/A

**Notes**

N/A



<b>Version: v2.0</b>	<b>Build: 22092310</b>
<b>Release Date: Sep 26, 2022</b>	

### **Applicable Products**

N/A

### **Supported Operating Systems**

N/A

### **New Features**

- Added support for Intrusion Prevention System (IPS) functionality through network security packages.
- Added support for the MXsecurity management software through MXsecurity agent packages.
- Added NAT Advanced Settings.
- Added Session Control Firewall Policy settings.

### **Enhancements**

- Updated the web user interface to the latest next-generation design.
- Layer 3-7 firewall policies are now object-based for better rule management.
- Improved firewall log categories and information layout for better readability.

### **Bugs Fixed**

N/A

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v1.2</b>	<b>Build: 22032514</b>
<b>Release Date: Mar 29, 2022</b>	

### **Applicable Products**

N/A

### **Supported Operating Systems**

N/A

### **New Features**

- Added support for built-in security packages.

### **Enhancements**

- Increased the maximum number of static multicast routes from 32 to 256.

### **Bugs Fixed**

- Exporting static multicast rules fails when the Static Multicast Route function is disabled.

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v1.1</b>	<b>Build: 21110913</b>
<b>Release Date: Dec 02, 2021</b>	

### **Applicable Products**

N/A

### **Supported Operating Systems**

N/A

### **New Features**

- Added support for the EDR-G9010 high-voltage (HV) models.
- Added support for the Turbo Ring V2 Coupling mode Layer 2 redundancy protocol.
- Added support for MSCHAPv2 authentication for RADIUS servers.

### **Enhancements**

- Improved the phrasing of package control operation error messages.

### **Bugs Fixed**

- CVE-2021-33909: vulnerability issue.
- The firewall and DoS event logs show incorrect information.
- Importing device configuration may fail under certain conditions.
- The local user database is invalid if RADIUS is disabled.
- The Drop Malformed Packets firewall function behaves irregularly when accessing the web UI.
- The web UI crashes when exporting the log file while the Malformed Packet function is enabled.
- HTTP would generate an error after upgrading the firmware.
- Enabling or disabling HTTPS(443) will disconnect users from the web UI.

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v1.0</b>	<b>Build: 21052417</b>
<b>Release Date: Jun 22, 2021</b>	

**Applicable Products**

N/A

**Supported Operating Systems**

N/A

**New Features**

The first release of the EDR-G9010 series.

**Enhancements**

N/A

**Bugs Fixed**

N/A

**Changes**

N/A

**Notes**

N/A