



## Firmware for MGate 5102-PBM-PN Series Release Notes

<b>Version: v2.3</b>	<b>Build: Build 21020512</b>
<b>Release Date: Mar 02, 2021</b>	

### Applicable Products

N/A

### Supported Operating Systems

N/A

### New Features

- Supports MCC Tool.

### Enhancements

- Supports MXconfig v2.6 and MXview v3.2.
- Enhanced log table placement.
- Enhanced cipher suite.
- Upgraded SQLite version to v3.33.0.

### Bugs Fixed

- Fixed the stuck system issue when the IP setting begins with a zero digit.
- Fixed CVE-2011-1473.
- Fixed the memory leak when receive receiving the wrong LLDP packets continuously.

### Changes

- The default setting for the telnet console has been disabled.

### Notes

N/A



<b>Version: v2.2</b>	<b>Build: N/A</b>
<b>Release Date: Apr 27, 2020</b>	

### **Applicable Products**

MGate 5102-PBM-PN, MGate 5102-PBM-PN-T

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

- Enhances the conversion performance of the PROFINET IO Device to PROFIBUS master.
- Extended mail alert user name length to 64-character.

### **Bugs Fixed**

- Fixed command injection cybersecurity vulnerability with built-in web console UI.
- Fixed TCP SACK panic vulnerabilities.

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v2.1</b>	<b>Build: Build 19052722</b>
<b>Release Date: Jul 02, 2019</b>	

### **Applicable Products**

MGate 5102-PBM-PN, MGate 5102-PBM-PN-T

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

- Upgraded OpenSSL version to v1.1.1b.
- Upgraded SQLite version to v3.27.2.
- Upgraded Net-SNMP version to v5.7.3.

### **Bugs Fixed**

- When parsing a PXC\_06CC.GSD file, user parameters were misallocated.
- When parsing an si04806a.GSD file, user parameters were misallocated.
- Web console would not respond when importing SE100E2E.GSD (Schneider Altivar Process 600).

### **Changes**

N/A

### **Notes**

- Before upgrading to firmware v2.1 or higher, please make sure you have already upgraded the unit to v2.0.



<b>Version: v2.0</b>	<b>Build: Build 18012622</b>
<b>Release Date: Mar 21, 2018</b>	

### **Applicable Products**

MGate 5102-PBM-PN, MGate 5102-PBM-PN-T

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

- Supports security features based on IEC-62443.
- Simplified telnet/ssh/serial console settings.
- Accessible IP List supports denying Web/Telnet/SSH console access.

### **Bugs Fixed**

- Issue importing SIE180BB.GSD (Siemens SIMEAS P).
- Issue parsing user parameters with WAGO 750-303.
- Incorrect topology display due to forwarding LLDP frames to another LAN port.

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v1.3</b>	<b>Build: Build 16070411</b>
<b>Release Date: Sep 09, 2016</b>	

### **Applicable Products**

MGate 5102-PBM-PN, MGate 5102-PBM-PN-T

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

- Supports Name/Contact/Location settings for MXconfig.
- Supports PROFIBUS module names over 32 characters long. MGate 5102-PBM-PN will truncate the displayed module name when its length is over the 32-character limitation specified by the PROFIBUS GSD specification.
- Changed the PROFIBUS Watchdog default value to 600 ms for baudrates of 500 kbit/sec or higher.
- HTTPS web server only supports TLSv1.0 to protect against DROWN attacks.
- Patched glibc to protect against GHOST vulnerability.
- The version of the exported GSDML file was updated to version 2.2.

### **Bugs Fixed**

- MGate could not communicate with some specific PROFIBUS slave devices due to only supporting a portion of the device's user parameters.
- Returned the wrong IP/netmask/gateway when SNMP read private MIB under DHCP mode.
- MGate 5102-PBM-PN could not communicate with some specific PROFIBUS slave devices due to incorrect parsing of a module's user parameter data.
- MGate 5102-PBM-PN could not communicate with ABB M102 slave (with ABB\_08DD.gsd.)

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v1.2</b>	<b>Build: Build 13083010</b>
<b>Release Date: N/A</b>	

### **Applicable Products**

MGate 5102-PBM-PN, MGate 5102-PBM-PN-T

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

- Supports "DCP-Signal" function.
- Passed PROFINET certification.
- Modified LLDP transmit interval to 5 seconds with TTL value 20.

### **Bugs Fixed**

- Cyclic I/O data error when the input and out slot are configured as interlaced.
- Return status of the second AR connection was not correct.
- PROFIBUS module handling of SLAVE\_INPUTS\_CHANGED event.

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v1.1</b>	<b>Build: Build 13031216</b>
<b>Release Date: N/A</b>	

**Applicable Products**

MGate 5102-PBM-PN, MGate 5102-PBM-PN-T

**Supported Operating Systems**

N/A

**New Features**

N/A

**Enhancements**

- Shows full model name in the header after logging in to the telnet/serial console.

**Bugs Fixed**

N/A

**Changes**

N/A

**Notes**

N/A



<b>Version: v1.0</b>	<b>Build: Build 13020716</b>
<b>Release Date: N/A</b>	

**Applicable Products**

MGate 5102-PBM-PN, MGate 5102-PBM-PN-T

**Supported Operating Systems**

N/A

**New Features**

- First release.

**Enhancements**

N/A

**Bugs Fixed**

N/A

**Changes**

N/A

**Notes**

N/A