



Firmware for TN-5500A Series (TN-5516A, TN-5518A) Release Notes

| | |
|-----------------------------------|------------------------|
| Version: v3.8 | Build: 20101414 |
| Release Date: Oct 01, 2019 | |

Applicable Products

TN-5518A, TN-5516A

Supported Operating Systems

N/A

New Features

- Added support for Security Guideline level 2.
- Added DNS Server functionality.

Enhancements

- Added compatibility drivers for new hardware components (Flash/RTC/CPU).

Bugs Fixed

- A Router Alert Option is added to all IGMP packets.
- The event log is unable to display dates after February 2038 (Y2K 2038).
- The "Set Device IP" function in the Web UI rejects valid IP addresses that contain the value "255".
- Under certain conditions, the Option-82 Relay function sends duplicate unicast DHCP Discover packets.
- The device cannot be accessed through HTTP/HTTPS after changing the device IP.
- The NTP query interval does not function properly.
- Incorrect language and information in the UI.

Changes

- The UI can now display both original (5 digits) and extended device serial numbers (12 digits).
- DHCP Option-82 Relay & Set Device IP now function per port.

Notes

N/A



| | |
|-----------------------------------|-------------------|
| Version: v3.7 | Build: N/A |
| Release Date: May 17, 2016 | |

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

NA

Enhancements

NA

Bugs Fixed

Fixed PoE user interface settings issue.

Changes

NA

Notes

N/A