

Fl.4, No. 135, Lane 235, Baoqiao Rd. Xindian Dist., New Taipei City 23145, Taiwan, R.O.C.

TEL: +886-2-8919-1230 FAX: +886-2-8919-1231 www.moxa.com

# MC-4510-C23 Series Component Compatibility Guide

A list of peripheral components suitable for use with the MC-4510-C23 series of computers

2016/01/15 V1.3



Fl.4, No. 135, Lane 235, Baoqiao Rd. Xindian Dist., New Taipei City 23145, Taiwan, R.O.C.

TEL: +886-2-8919-1230 FAX: +886-2-8919-1231 www.moxa.com

# **Copyright Notice**

©2016 Moxa Inc.

All rights reserved.

Reproduction without permission is prohibited.

## **Trademarks**

The MOXA logo is a registered trademark of Moxa Inc.

All other trademarks or registered marks in this manual belong to their respective manufacturers.

## **Disclaimer**

Information in this document is subject to change without notice and does not represent a commitment on the part of Moxa.

Moxa provides this document as is, without warranty of any kind, either expressed or implied, including, but not limited to, its particular purpose. Moxa reserves the right to make improvements and/or changes to this manual, or to the products and/or the programs described in this manual, at any time.

Information provided in this manual is intended to be accurate and reliable. However, Moxa assumes no responsibility for its use, or for any infringements on the rights of third parties that may result from its use.

This document might contain unintentional technical or typographical errors. Changes are periodically made to the information herein to correct such errors, and these changes are incorporated into new editions of the publication.

# **Technical Support Contact Information**

### www.moxa.com/support

Tel: +86-21-5258-9955

Moxa Americas Moxa China (Shanghai office)

Toll-free: 1-888-669-2872 Toll-free: 800-820-5036

Fax: +1-714-528-6778 Fax: +86-21-5258-5505

Moxa Europe Moxa Asia-Pacific

Tel: +49-89-3 70 03 99-0 Tel: +886-2-8919-1230

Fax: +49-89-3 70 03 99-99 Fax: +886-2-8919-1231 Moxa India

Tel: +91-80-4172-9088

Tel: +1-714-528-6777

Fax: +91-80-4132-1045

MC-4510-C23 Series CCG Page 2 of 9



Fl.4, No. 135, Lane 235, Baoqiao Rd. Xindian Dist., New Taipei City 23145, Taiwan, R.O.C.

TEL: +886-2-8919-1230 FAX: +886-2-8919-1231 www.moxa.com

## 1. Introduction

This document lists hardware components that are proven to provide the performance listed in the specification when used with the Moxa MC-4510-C23 series of embedded computers, or computers that share basic design features with the MC-4510-C23 series. Moxa computers come with multiple peripheral options and are engineered to work with components having different hardware specifications. This flexibility could sometimes lead to compatibility issues. When used with the MC-4510-C23 series of embedded computers, peripherals from one manufacturer may not work as well as the ones made by another manufacturer. Moxa provides this list of MC-4510-C23 series-compatible components, so that users can be certain of a reliable performance from the MC-4510-C23 series, when used with the components listed in this document.

# 2. Testing Methods

To validate that a component meets the Moxa standards for quality and environmental tolerance, the following five key compatibility tests are run:

- Ambient Temperature Burn-In
- Low Temperature Hard Starts
- Heat/Humidity Burn-In
- Cyclic High-Low Temperature Burn-In
- Vibration Test

# **Ambient Temperature Burn-In**

The component is mounted on to a MC-4510-C23 computer and put through a series of stress tests at an ambient temperature of around 25°C, for a specified period of time. Test periods are determined based on the class of peripherals being tested.

# Low Temperature Hard Start

The component is mounted on to an unpowered MC-4510-C23 computer and then the system is booted up at an extremely low temperature. The designated temperature depends on the computer model being tested.

# **Heat/Humidity Burn-In**

The components is mounted on to a MC-4510-C23 computer, placed in a temperature- and humidity-controlled enclosure, and then put through the burn-in test for a specified period of time. The temperature, humidity, and time targets vary depending on the specification of the computer model used in the test.



Fl.4, No. 135, Lane 235, Baoqiao Rd. Xindian Dist., New Taipei City 23145, Taiwan, R.O.C.

TEL: +886-2-8919-1230 FAX: +886-2-8919-1231 www.moxa.com

## **Cyclic High-Low Temperature Burn-In**

The components is mounted on to a MC-4510-C23 computer, placed in a temperature controlled enclosure, and then put through the burn-in test as the temperature are cyclically varied from very high to very low and back again, over a specified period of time. The target temperature range and the duration of the test can vary depending on the specification of the computer model used in the test.

## **Vibration Test**

The component is mounted on to a MC-4510-C23 computer that is bound inside an electromagnetic vibrator, and then put through random vibration tests along three orthogonal axes: longitudinal, transverse, and vertical. The vibration tests are compliant with the EN50155/IEC61373 vibration standards.

# 3. Storage Endurance

Storage media, such as SSDs, CF cards, SD cards, Disk on Module, and Cfast, are composed of different electrical components. The main electrical components are NAND-Flash memory and NAND-Flash controller, which impact the storage endurance and lifespan of storage media.

# **NAND-Flash Memory Endurance**

All NAND-Flash memories have a limit on their physical Program and Erase (P/E). The P/E cycle as well as the erase count can be used to determine this limit. For example, SLC (Single level cell) flash memory has a 60,000 P/E cycle, MLC (Multi-level cell) flash memory has a 3,000 P/E cycle, and TLC NAND Flash memory has up to a 1,000 P/E cycle. Each type of flash memory has a different endurance level, which is why the storage lifespan is based on the flash memory type. Storage that uses SLC type flash memory could have the best endurance level compared with the MLC type storage. SLC storage usually comes with a 5-year OEM warranty (the actual warranty period depends on the original manufacturer). MLC storage only comes with a 1- to 3-year warranty. The major differences between SLC and MLC are: (a) The SLC NAND Flash has a lifespan that is around 20 times that of an MLC, and (b) The price can differ by a factor of 4 to 5. The SLC type of storage is recommended for systems that are expected to have high reliability, and for application that need to frequently write data to a storage medium.



Fl.4, No. 135, Lane 235, Baoqiao Rd. Xindian Dist., New Taipei City 23145, Taiwan, R.O.C.

TEL: +886-2-8919-1230 FAX: +886-2-8919-1231 www.moxa.com

# Terabytes Written (TBW)

TBW is the unit used to evaluate SSD endurance. In actual applications, storage is used for routine operations and data access. Therefore the physical P/E cycle is not appropriate for describing the total rewritable data capacity. The management efficiency of the storage controller also affects the total rewritable data capacity result. For these reasons, Joint Electron Device Engineering Council (JEDEC) has defined a standard for SSD endurance evaluation called JESD218, which uses TBW to measure the endurance of the storage memory. By referring to this TBW value, users can easily estimate the storage specification and select a suitable storage for real-use cases. For example, when routine operations need a maximum of 20 GB and the expected storage lifespan is 3 years, the total rewritable data demand would be 21.9 TBW (20 GB x 365 x 3). In this case, a storage that has more than 21.9 TBW will meet the requirement. We recommend selecting a storage media with a TBW that is greater than the calculated value.

# 3. Declaration for Liability Exclusion

The specifications, warranty terms, and liability of items listed in this guide are the sole responsibility of the original manufacturers. Moxa does not take any responsibility in this regard. Please visit the manufacturers' official websites for up-to-date product information before purchasing the components.

# 4. Compatible Components

Peripheral components that have been tested and found suitable for use with the MC-4510-C23 series of computers are listed in this section. Check the following table for test codes and their descriptions:

Test Code	Description						
Α	The component has passed the ambient temperature verification test						
В	The component has passed the low temperature verification test						
С	The component has passed the heat/humidity verification test						
D	The component has passed the cyclic high-low temperature verification test						
Г	The component has not been tested, but is similar to another component that						
E	has been tested in terms of its material and design.						
F	The component has passed the vibration verification test						



Fl.4, No. 135, Lane 235, Baoqiao Rd. Xindian Dist., New Taipei City 23145, Taiwan, R.O.C.

SSD										
Vendor	Size	Moxa's PN	Vendor's PN	Flash Brand	Flash Spec	Controller	Firmware	Warranty years	Warranty exclusion	Test Codes
InnoDisk	16 GB	N/A	D2ST-16GJ13W1	N/A	MLC	N/A	N/A	2 years	Endurance > 3,000	B, C, D
Memoright	32 GB	N/A	MRSAJ6C032GC125C00	Micron	MLC	JMF612	MRV1.1.5	2 years	Endurance > 3,000	Е
Memoright	64 GB	N/A	MRSAJ6C064GC125C00	Micron	MLC	N/A	N/A	2 years	Endurance > 3,000	B, C, D
Transcend	16 GB	N/A	TS16GSSD500	Samsung	SLC	JM616	120820	2 years	N/A	Е
Transcend	32 GB	N/A	TS32GSSD500	Samsung	SLC	JM616	120820	2 years	N/A	Е
Transcend	64 GB	N/A	TS64GSSD320	SanDisk/ Micron	MLC	SF2281	N/A	2 years	N/A	Е
Transcend	64 GB	N/A	TS64GSSD500	Samsung	SLC	JM616	120820	2 years	N/A	А
Transcend	128 GB	N/A	TS128GSSD320	SanDisk/ Micron	MLC	SF2281	N/A	2 years	N/A	Е
Transcend	256 GB	N/A	TS256GSSD320	SanDisk/ Micron	MLC	SF2281	N/A	2 years	N/A	А
Apacer	64 GB	N/A	AP64GAS510SB	N/A	MLC	N/A	N/A	2 years	Endurance > 3,000	А



Fl.4, No. 135, Lane 235, Baoqiao Rd. Xindian Dist., New Taipei City 23145, Taiwan, R.O.C.

CF										
Vendor	Size	Moxa's PN	Vendor's PN	Flash Brand	Flash Spec	Controller	Firmware	Warranty years	Warranty exclusion	Test Codes
Transcend	128 MB	N/A	TS128MCF200I	Samsung	MLC	SM2232AD	N/A	2 years	N/A	Е
Transcend	256 MB	N/A	TS256MCF200I	Samsung	MLC	SM2232AD	N/A	2 years	N/A	Е
Transcend	512 MB	N/A	TS512MCF200I	Samsung	MLC	SM2232AD	N/A	2 years	N/A	Е
Transcend	1 GB	N/A	TS1GCF133	SanDisk/ Micron	MLC	SM2232AD	N/A	2 years	N/A	Е
Transcend	1 GB	N/A	TS1GCF200I	Samsung	MLC	SM2232AD	N/A	2 years	N/A	Е
Transcend	2 GB	N/A	TS2GCF133	SanDisk/ Micron	MLC	SM2232AD	N/A	2 years	N/A	Е
Transcend	2 GB	N/A	TS2GCF200I	Samsung	MLC	SM2232AD	N/A	2 years	N/A	Е
Transcend	4 GB	N/A	TS4GCF133	SanDisk/ Micron	MLC	SM2232AD	N/A	2 years	N/A	Е
Transcend	4 GB	N/A	TS4GCF200I	Samsung	MLC	SM2232AD	N/A	2 years	N/A	А
Transcend	8 GB	N/A	TS8GCF400	SanDisk/ Micron	MLC	SM2236AC	N/A	2 years	N/A	E
Transcend	8 GB	N/A	TS8GCF133	SanDisk/ Micron	MLC	SM2232AD	N/A	2 years	N/A	E
Transcend	8 GB	N/A	TS8GCF200I	Samsung	MLC	SM2232AD	N/A	2 years	N/A	E
Transcend	16 GB	N/A	TS16GCF1000	SanDisk/ Micron	MLC	SM2232ENAC	N/A	2 years	N/A	E
Transcend	16 GB	N/A	TS16GCF400	SanDisk/ Micron	MLC	SM2236AC	N/A	2 years	N/A	Е
Transcend	16 GB	N/A	TS16GCF133	SanDisk/ Micron	MLC	SM2232AD	N/A	2 years	N/A	Е
Transcend	16 GB	N/A	TS16GCF200I	Samsung	MLC	SM2232AD	N/A	2 years	N/A	Е
Transcend	32 GB	N/A	TS32GCF1000	SanDisk/ Micron	MLC	SM2236AC	N/A	2 years	N/A	А
Transcend	32 GB	N/A	TS32GCF400	SanDisk/ Micron	MLC	SM2236AC	N/A	2 years	N/A	А
Transcend	32 GB	N/A	TS32GCF133	SanDisk/ Micron	MLC	SM2232AD	N/A	2 years	N/A	E
Transcend	32 GB	N/A	TS32GCF200I	Samsung	MLC	SM2232AD	N/A	2 years	N/A	А
Apacer	32 GB	N/A	AP-CF032GL9FS-NR	N/A	MLC	N/A	N/A	2 years	Endurance > 3,000	А
Apacer	16 GB	N/A	AP-CF016GL9FS-NR	N/A	MLC	N/A	N/A	2 years	Endurance > 3,000	E
Apacer	8 GB	N/A	AP-CF008GL9FS-NR	N/A	MLC	N/A	N/A	2 years	Endurance > 3,000	Е
Apacer	4 GB	N/A	AP-CF004GL9FS-NR	N/A	MLC	N/A	N/A	2 years	Endurance > 3,000	Е
Apacer	32 GB	N/A	AP-CF032GLAFS-NR	N/A	MLC	N/A	N/A	2 years	Endurance > 3,000	А
Apacer	16 GB	N/A	AP-CF016GLAFS-NR	N/A	MLC	N/A	N/A	2 years	Endurance > 3,000	Е
Apacer	8 GB	N/A	AP-CF008GLAFS-NR	N/A	MLC	N/A	N/A	2 years	Endurance > 3,000	E
Silicon Power	2 GB	N/A	SP002GBCFI000V711T	Toshiba	SLC	SMI	N/A	3 years	N/A	А
Silicon Power	1 GB	N/A	SP001GBCFI000V711T	Toshiba	SLC	SMI	N/A	3 years	N/A	E
Silicon Power	4 GB	N/A	SP004GBCFI000V602T	Toshiba	SLC	SMI	N/A	3 years	N/A	А
Silicon Power	2 GB	N/A	SP002GBCFI000V601T	Toshiba	SLC	SMI	N/A	3 years	N/A	E
Silicon Power	1 GB	N/A	SP001GBCFI000V601T	Toshiba	SLC	SMI	N/A	3 years	N/A	E



Fl.4, No. 135, Lane 235, Baoqiao Rd. Xindian Dist., New Taipei City 23145, Taiwan, R.O.C.

	DRAM									
Vendor	Size	Moxa's PN	Vendor's PN	Interface	Chip Brand	Speed	Test Codes			
DSL	1 GB	N/A	D3SH28081XH18AB	DDR3	Hynix	1066	B, C, D			
DSL	2 GB	N/A	D3SH56081XH18AB	DDR3	Hynix	1066	B, C, D			
DSL	2 GB	N/A	D3SE28082XH18AB	DDR3	ELPIDA	1066	B, C, D			
DSL	4 GB	N/A	D3SH56082XH18AB	DDR3	Hynix	1066	B, C, D			
InnoDisk	2 GB	N/A	M3SN-2GHJCCM7-B	DDR3	Hynix	1333	B, C, D			
InnoDisk	4 GB	N/A	M3SN-4GHJDCM7-B	DDR3	Hynix	1333	B, C, D			
Unigen	2 GB	N/A	UG25U6400M8SU-ACA	DDR3	Hynix	1333	B, C, D			
Unigen	4 GB	N/A	UG51U6400N8SU-ACF	DDR3	Hynix	1333	B, C, D			



Fl.4, No. 135, Lane 235, Baoqiao Rd. Xindian Dist., New Taipei City 23145, Taiwan, R.O.C.

HDD										
Vendor	Size	Moxa's PN Vendor's PN Controller		Firmware	Test Codes					
HGST	1 TB	N/A	HCC541010A9E680	N/A	N/A	А				
HGST	1 TB	N/A	HTS541010A9E680	N/A	N/A	А				
WD	750 GB	N/A	WD7500BPKT	N/A	N/A	А				
WD	1 TB	N/A	WD10JUCT	N/A	N/A	А				
WD	1 TB	N/A	WD10JPVT	N/A	N/A	А				
WD	1 TB	N/A	WD10SPCX	N/A	N/A	А				
Samsung	2 TB	N/A	ST2000LM003	N/A	N/A	А				
HGST	1 TB	N/A	HTS721010A9E630 / 0J22423	N/A	N/A	А				
HGST	500 GB	N/A	HTS725050A7E630 / 0J38075	N/A	N/A	А				
Samsung	2 TB	N/A	ST2000LM003	N/A	N/A	А				
HGST	1 TB	N/A	HTS721010A9E630 / 0J22423	N/A	N/A	А				
HGST	500 GB	N/A	HTS725050A7E630 / 0J38075	N/A	N/A	А				
HGST	1 TB	N/A	HTS541010A9E680	N/A	N/A	А				